

UT-ID 1.1.11.1-3

UNITEC Repair of the OVF 30 Drive

NONDISCLOSURE WARNING

This work contains proprietary information and is the property of UNITEC. It is distributed only to those employees with a need to know the information and may not be reproduced, disclosed, or distributed to any person outside the employ of UNITEC without written authorization from an officer thereof. UNITEC competitors, customers, former employees, retirees, members of the general public and consultants not bound by a written nondisclosure agreement are among those outside the employ of UNITEC. In the event that an employee in the possession of this work no longer needs the information, retires, resigns, is terminated or laid off from UNITEC, or in the event that a person outside the employ of UNITEC comes into possession of this work, such employee or person should destroy the work or return it to UNITEC.

Any unauthorized reproduction, disclosure or distribution by any person of any portion of this work may be a breach of a duty owed by such person to UNITEC and could result in damages actionable at law.

PROHIBITION ON COPYING

Any unauthorized reproduction, disclosure or distribution of copies by any person of any portion of the work may be a violation of Copyright Law of the United States of America and other countries, could result in the awarding of Statutory Damages of up to \$250,000 (17 USC 504) for infringement and may result in further civil and criminal penalties. All rights reserved.

PUBLICATION CATALOGING DATA

First Issue: November 2014
Master Index Control Number:
Part Number: UT-ID 1.1.11.1-3

Comments or questions about the information contained in this publication should be directed to:

UNITEC
212 West Newberry Road
Bloomfield, CT 06002
(800) 328-7840 Phone
(860) 286-1625 Fax

Unpublished Work - © UNITEC 2014

Affected Drives

OVF Drive P/N	Description
A_A21290AK_	70A, 480 VAC, OVF
A_A21290BJ_	90A, 480 VAC, OVF
A_A21290BA_	120A, 480 VAC, OVF
A_A21290BM_	210A 480 VAC, OVF




Figure 1: OVF Drive

Description

Prior to shipping a defective drive for repair, remove and safely store the U5 chip in an electrostatic discharge (ESD) safe container. U5 contains the contract specific information for the drive. In case the U5 is lost or damaged, Otis local office will have to recreate this contract chip. Every effort will be made to repair your defective drive, due to multiple iterations of the hardware and software. If it is not possible to repair your drive, you will be notified.

Required Tools

- ✓ Chip puller p/n VP-766100 or equivalent

Instructions for Removing U5 EEPROM on the A*A26800VA Processor Board

1. Remove the U5 EEPROM on the A*A26800VA processor board.
2. Use a chip puller (p/n VP-766100) to remove the U5 EEPROM from the A*A26800VA board.
3. Put the chip inside an anti-static holder to avoid electrostatic discharge (ESD) and damaging pins.
4. Retain the software to reinstall into the drive when it returns.
5. When you receive the drive from the repair facility, install the U5 EEPROM in the A*A26800VA board.
6. Verify that the “notch” on U5 is oriented to the left when viewing the circuit board from the “right-side up.”

UNITEC REPAIR OF THE OVF 30 DRIVE




Figure 2: VF Drive Board Location